HOW TO PUT ON AND TAKE OFF

Personal Protective Equipment (PPE)



How to put on PPE (when all PPE items are needed)



Step 1

- Identify hazards & manage risk. Gather the necessary PPE.
- Plan where to put on & take off PPE.
- Do you have a buddy? Mirror?
- Do you know how you will deal with waste?



Step 2

- Put on a gown.



Step 3a

- Put on face shield.



- Put on medical mask and eye protection (e.g. eye visor/goggles)







Note: If performing an aerosol-generating procedure (e.g. aspiration of respiratory tract, intubation, resuscitation, bronchoscopy, autopsy), a particulate respirator (e.g. US NIOSH-certified N95, EU FFP2, or equivalent respirator) should be used in combination with a face shield or an eye protection. Do user seal check if using a particulate respirator.

OR



Step 4

- Put on gloves (over cuff).

How to take off PPE



Step 1

- Avoid contamination of self, others & the environment
- Remove the most heavily contaminated items first

Remove gloves & gown

- Peel off gown & gloves and roll inside, out
- Dispose gloves and gown safely



Step 2


- Perform hand hygiene



Step 3a

If wearing face shield:

- Remove face shield from behind
- Dispose of face shield safely



Step 3b

If wearing eye protection and mask:

- Remove goggles from behind
- Put goggles in a separate container for reprocessing
- Remove mask from behind and dispose of safely



Step 4

- Perform hand hygiene